

0000 49239



Department of Energy

ROCKY FLATS FIELD OFFICE
P.O. BOX 928
GOLDEN, COLORADO 80402-0928

DEC 19 1994

94-DOE-12639

Mr. Martin Hestmark
U. S. Environmental Protection Agency, Region VIII
ATTN: Rocky Flats Project Manager, 8HWM-FF
999 18th Street, Suite 500
Denver, Colorado 80202-2405

Mr. Joe Schieffelin
Hazardous Waste Facilities Unit Leader
Colorado Department of Public Health and Environment
4300 Cherry Creek Drive South
Denver, Colorado 80222-1530

Gentlemen:

In compliance with the Interagency Agreement between the Department of Energy, the U.S. Environmental Protection Agency, and the Colorado Department of Public Health and Environment, the enclosed November report summarizes the status of environmental restoration activities as of November 31, 1994.

If you have any questions or comments relative to this report, please feel free to contact Howard Rose at 966-5917.


Sincerely,

A handwritten signature in cursive script, reading "Steven W. Slaten".

Steven W. Slaten
LAG Project Coordinator
Environmental Restoration

Enclosure

cc w/o Enclosure:
H. Rose, ER, RFFO
W. Hunt, SAIC



DOCUMENT CLASSIFICATION
REVIEW WAIVER PER
CLASSIFICATION OFFICE

A-SW-001464



Department of Energy

ROCKY FLATS FIELD OFFICE
P.O. BOX 928
GOLDEN, COLORADO 80402-0928

CHWMA-FFR

DEC 20 1994

DEC 19 1994

94-DOE-12639 --

Mr. Martin Hestmark
U. S. Environmental Protection Agency, Region VIII
ATTN: Rocky Flats Project Manager, 8HWM-FF
999 18th Street, Suite 500
Denver, Colorado 80202-2405


Mr. Joe Schieffelin
Hazardous Waste Facilities Unit Leader
Colorado Department of Public Health and Environment
4300 Cherry Creek Drive South
Denver, Colorado 80222-1530

Gentlemen:

In compliance with the Interagency Agreement between the Department of Energy, the U.S. Environmental Protection Agency, and the Colorado Department of Public Health and Environment, the enclosed November report summarizes the status of environmental restoration activities as of November 31, 1994.

If you have any questions or comments relative to this report, please feel free to contact Howard Rose at 966-5917.

Sincerely,


Steven W. Slaten
IAG Project Coordinator
Environmental Restoration

Enclosure

cc w/o Enclosure:
H. Rose, ER, RFFO
W. Hunt, SAIC